

## Finishing table



is made in Italy

GRAIN	ADJUSTMENT KNOB POSITION	FINISHING
<b>Oat</b>	1	Partially crushed
	1-3	Raw crushing (flakes)
	3	Medium crushing (flakes)
	3-5	Medium-fine crushing (flakes)
	5	Fine crushing (flakes)
	6	Superfine crushing (flour)
<b>Barley</b>	1	Cracking
	1-3	Raw crushing (flakes)
		Medium crushing (flakes)
	Sequence 1-3-6	Flour
<b>Malted barley</b>	3	Homebrewing finishing
<b>Malted spelt</b>	1-3	Homebrewing finishing
<b>Buckwheat</b>	Sequence 1-6	Flour

GRAIN	ADJUSTMENT KNOB POSITION	FINISHING
<b>Durum wheat</b>	Sequence 3-5-6	Flour
	1	Partially crushed
<b>Kamut</b>	Sequence 3-5-6	Flour
	1	Partially crushed
<b>Millet</b>	6	Flour
<b>Rice</b>	Sequence 1-3-5-6	Flour
<b>Spelt</b>	Sequence 1-3-6	Flour
	Sequence 1-6	Flour
<b>Quinoa</b>	Sequence 5-6	Flour
<b>Pepper</b>	Sequence 1-6	Milling
<b>Salt</b>	3	Milling